

Tower Alert – 10 Nov 2003

Tower Leg Damage Due to Corrosion

**Attention Tower Professionals:
Be aware of possibility of corrosion inside tower legs.**



Corrosion inside tower leg – Nov 2003



Note leg wall thickness – should be schedule 40. Nov 2003



Broken leg from same tower – Normal leg thickness – Nov 2003